
Take-up Winders / 拉卷型导丝器




A/NO. AP-1478

MAT. Al_2O_3 (A997)


① *Take-up Winder*
Art. No. FT997-1307

② *Plastic Shoe (Nylon)*
Art. No. 1111-T-1010



= Thread Guide Surface

Take-up Winders / 拉卷型导丝器




A/NO. AP-1605

MAT. Al_2O_3 (A997)


① *Take-up Winder*
Art. No. FT997-1307

② *Plastic Shoe (Nylon)*
Art. No. 1111-T-1058



= Thread Guide Surface

Take-up Winders / 拉卷型导丝器




A/NO. AP-1557

MAT. Al_2O_3 (A997)


① *Take-up Winder*
Art. No. FT997-1209

② *Plastic Shoe (Nylon)*
Art. No. 1111-T-1045



= Thread Guide Surface

Take-up Winders / 拉卷型导丝器




A/NO. AP-1477

MAT. Al_2O_3 (A997)


① *Take-up Winder*
Art. No.FT997-1307

② *Plastic Shoe (Nylon)*
Art. No. 1111-T-1009



= Thread Guide Surface

Take-up Winders / 拉卷型导丝器




A/NO. AP-1476

MAT. Al_2O_3 (A997)


① *Take-up Winder*
Art. No. FT997-1213


② *Plastic Shoe (Nylon)*
Art. No. 1111-T-1008



= Thread Guide Surface

Take-up Winders / 拉卷型导丝器






A/NO. FT997-1307

MAT. Al_2O_3 (A997)

= Thread Guide Surface

Take-up Winders / 拉卷型导丝器







A/NO. FT997-1209

MAT. Al_2O_3 (A997)

= Thread Guide Surface

Take-up Winders / 拉卷型导丝器







A/NO. FT997-1306

MAT. Al_2O_3 (A997)

= Thread Guide Surface

Take-up Winders / 拉卷型导丝器






A/NO. FT997-1213

MAT. Al_2O_3 (A997)

= Thread Guide Surface

Take-up Winders / 拉卷型导丝器






A/NO. FT997-1313

MAT. Al_2O_3 (A997)

= Thread Guide Surface

Take-up Winders / 拉卷型导丝器






A/NO. FT997-1215

MAT. Al_2O_3 (A997)

= Thread Guide Surface

Take-up Winders / 拉卷型导丝器






A/NO. FT997-1216

MAT. Al_2O_3 (A997)

= Thread Guide Surface

Take-up Winders / 拉卷型导丝器






A/NO. FT997-1219

MAT. Al_2O_3 (A997)

= Thread Guide Surface

Take-up Winders / 拉卷型导丝器






A/NO. FT997-1218

MAT. Al_2O_3 (A997)

= Thread Guide Surface

Take-up Winders / 拉卷型导丝器







A/NO. FT997-1220

MAT. Al_2O_3 (A997)

= Thread Guide Surface

Take-up Winders / 拉卷型导丝器






A/NO. FT997-1170

MAT. Al_2O_3 (A997)

= Thread Guide Surface

Take-up Winders / 拉卷型导丝器






A/NO. TO-1502

MAT. TiO_2 (Tianit)

= Thread Guide Surface

Take-up Winders / 拉卷型导丝器






A/NO. FT970-1472

MAT. Al_2O_3 (Slim)

= Thread Guide Surface

Take-up Winders / 拉卷型导丝器






A/NO. FT970-1492

MAT. Al_2O_3 (Slim)

= Thread Guide Surface

Take-up Winders / 拉卷型导丝器






A/NO. FT997-1237

MAT. Al_2O_3 (A997)

= Thread Guide Surface

Take-up Winders / 拉卷型导丝器






A/NO. FT997-1239

MAT. Al_2O_3 (A997)

= Thread Guide Surface

Take-up Winders / 拉卷型导丝器







A/NO. FT970-1460

MAT. Al_2O_3 (Slim)

= Thread Guide Surface

Take-up Winders / 拉卷型导丝器






A/NO. FT970-1457

MAT. Al_2O_3 (Slim)

= Thread Guide Surface

Take-up Winders / 拉卷型导丝器







A/NO. FT997-1287

MAT. Al_2O_3 (A997)

= Thread Guide Surface

Take-up Winders / 拉卷型导丝器






A/NO. FT997-1242

MAT. Al_2O_3 (A997)

= Thread Guide Surface

Take-up Winders / 拉卷型导丝器






A/NO. FT997-1280

MAT. Al_2O_3 (A997)

= Thread Guide Surface

Take-up Winders / 拉卷型导丝器






A/NO. FT997-1315

MAT. Al_2O_3 (A997)

= Thread Guide Surface

Take-up Winders / 拉卷型导丝器






A/NO. FT997-1507

MAT. Al_2O_3 (A997)

——— = Thread Guide Surface

Take-up Winders / 拉卷型导丝器







A/NO. FT997-1508

MAT. Al_2O_3 (A997)

——— = Thread Guide Surface

Take-up Winders / 拉卷型导丝器







A/NO. FT970-8983

MAT. Al_2O_3 (Slim)

——— = Thread Guide Surface

Take-up Winders / 拉卷型导丝器






A/NO. FT997-1314

MAT. Al_2O_3 (A997)

——— = Thread Guide Surface

Take-up Winders / 拉卷型导丝器






A/NO. FT997-1266

MAT. Al_2O_3 (A997)

——— = Thread Guide Surface

Take-up Winders / 拉卷型导丝器





A/NO. FT990-1266

MAT. Al_2O_3 (A99S)

——— = Thread Guide Surface