


型号表示方法
 Model indication method

1 型号 Model

1	1000型
2	2000型
3	3000型

2 压力范围 Pressure Range

1	0.1MPa
3	0.5MPa
5	0.9MPa

3 电源电压 Supply voltage

0	DC24V
1	DC12~15V

4 输入信号 Input signal

0	电流型DC4~20mA(汇式) Current type DC4~20mA (sink type)
1	电流型DC0~20mA(汇式) Current type DC0~20mA (sink type)
2	电压型DC0~5V Voltage type DC0~5V
3	电压型DC0~10V Voltage type DC0~10V
40	4点预置输入 4-point preset input
52	16点预置输入 16-point preset input (开关输出·NPN输出) (switch output, NPN output)
53	16点预置输入 16-point preset input (开关输出·PNP输出) (switch output, PNP output)
MB	ModBus通讯型 ModBus communication type

5 监控输出 Monitor output

1	模拟输出DC1~5V Analog output DC1~5V
2	开关输出·NPN输出 Switch output NPN output
3	开关输出·PNP输出 Switch output·PNP output
4	模拟输出DC4~20mA(汇式) Analog output DC4~20mA (sink type)

※当输入信号选择预置输入型或者通讯型，无输出信号选择
 ※When the input signal is set to preset input type or communication type, there is no output signal selection.

6 连接螺纹的种类 Type of connection thread

无记号 No mark	Rc
N	NPT
T	NPTF
F	G

7 连接口径 Connection diameter

1	1/8(1000形式) 1/8(1000 form)
2	1/4(1000,2000,3000形式) 1/4(1000,2000,3000form)
3	3/8(2000,3000形式) 3/8(2000,3000form)
4	1/2(3000形式) 1/2(3000form)

8 附件(托架)Accessories (bracket)

无记号 No mark	无托架 Without bracket
B	平板型托架 Flat bracket
C	L型托架 L-Bracket

9 电缆插头的种类 Cable plug types

S	直线型3m Straight type 3m
L	直角型3m Straight type 3m
N	无电缆插头 No cable plug

10 压力显示单位 Pressure display unit

无记号 No mark	Mpa
2	kgf/cm ²
3	bar
4	psi
5	kPa

11 电流类型 Current type

无记号 No mark	汇式 Convergence
XSource	源式 Source